

Oil Field Environmental Incident Summary

Incident: 20150514084656 **Date/Time of Notice:** 05/14/2015 08:46

Responsible Party: NORTH PLAINS ENERGY, LLC

Well Operator: NORTH PLAINS ENERGY, LLC

Well Name: SMOKY BUTTE 2 SWD

Field Name: SMOKY BUTTE

Well File #: 10842

Date Incident: 5/13/2015 **Time Incident:** 05:00

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 100

Sec: 4

Qtr:

Location Description: Well site

Submitted By: Clayton Miller

Received By:

Contact Person: Clayton Miller
1888 SHERMAN ST STE 375
DENVER, CO 80203

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	45	Barrels	30	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Approximately 2' x 6' of area on the side of the berms outside the secondary containment was wet.

Potential Environmental Impacts:

none

Action Taken or Planned:

Standing water was recovered by vacuum truck. Approximately 10 cu yards of wet soil on the well site was removed.

Wastes Disposal Location: Secure 13-Mile Landfill

Agencies Involved:

Updates

Date: 5/14/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.